



铅、镉空芯阴

铅、镉元素检测的重要性

铅、镉暴露

1)))g



仪器

AAS-S200 40μl 360μl 1.5min 20232220572

试剂

() 30 36mLX200 3 / 1.0gX6 / 20222400130

铅、镉对人体的损害

) ; ()

0.5gX3 (1 2 4);
0.5gx3 (3 5 6);
0.5gX6 (1);
0.5gX6 (2);

g